

Report ID: 26,454,630 2 Version: 12 Dec 2024 Created:

Make:	Hyundai	Model:	Getz	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2004	Registration:		Reg Expiry:	08 Feb 2025	Engine	1 435	1 dii	
WoF Expiry:		Odometer:	266,020 Kms	Good No:	26454630	Oil level	~		1
VIN:	KMHBU51AR5U265936	Next Service:	-	Service Histor		Smoke & fumes	~		+
			-,			Performance	~		-
	port is not a warranty		for one and miles a	Doute house not	heen dismonthed or	Noise	~		+
diagnostic te	s a guide only. Consid sting undertaken. The	vehicle has beer	n driven up to 50km/	h from cold. The '	Vendor recommends	Cooling System	•		<u> </u>
a full mechar	nical inspection prior to	purchase and t	his can be arranged f	or an additional o	harge.	Coolant condition	~		1
					DDTCC	Performance	~		+
Key:	s sc s	-0	P SC		D PT SC	Radiator / Hoses (visual)	~		<u> </u>
S = scratch	AT.			NG G	<u>که</u>	Transmission			1
D = dent R = rust	S D SC	1		715	S PT SC	Operation	~		
PT = paint def		IT I		$\left[\left(\right) \right]$		Noise	~		+
C = crack					P SC	Clutch			~
P = pin dent	PSC de			$\langle \rangle$	74116	CV joints	~		
* = decals		10		Ta		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			1
w – signinean	D SC S	- C	S PT SC S P SC		S D SC	Performance	~		T
Body Insi	pection Comments	Note: son	ne defects & blemishe	s may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread	ed tread depth of tyres)		
Front bumper needs refitted. RR door trim loose Paint defect on LH mirror. Dents in both sills.						Left front	5	.5	mm
Crack in windscreen.						Right front	4	.5	mm
Paint defect on rear spoiler.						Left rear	3.0		mm
Conditions During Body Inspection: Dry					Right rear	2.5		mm	
						Spare Yes			
<u>Under Ca</u>	irriage & Under Boi	nnet Inspectio	on Comments			Suspension			
Engine oil l	eak.					Suspension performance	~		
Major trans	mission leak.					Steering performance		~	
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Average					Tail lights	~		<u> </u>
	, we rage					Indicators	~		_
Panels	Average, I	Roof lining falling	down			Dashboard warning lights	~		<u> </u>
Dashboa	ard Average					Wipers (front & rear)	~		─
						Window winder FL	~		—
General (Comments					Window winder FR	~		<u> </u>
					Window winder RL	v		<u> </u>	
Pulley area noise. Steering knock.					Window winder RR	v			
						Rear view mirrors	v		┼──
						Radio (basic test only) CD (basic test only)	v		+
						Number of keys	1		<u> </u>
Decal	ditions Devision T	+ Duit	<u> </u>			Central locking	· ·		T
KOAG CON	ditions During Tes	t Drive:	Dry			Remote locking	~		+
Engine Ti	ming Mechanism:	Cambel	t			Sat. Nav. (basic test only)	-		~
-	of Cam Belt Replac		'es	Kms: 17	1,120	Reversing camera			v v
	•								
Inspecte	d by: Caleb Spicer Le	e				Date: 02 Dec 20	24		
I have read	and understood th	is condition o	uide. Name:			Signature:			

I have read and understood this condition guide.

Name: