

Make:	Nissan	Model:	Navara	Body Style:	Utility		Pass	Fail	N/A	
Year:	2014	Registration:	HHJ28	Reg Expiry:	05 Aug 2024	Engine		1		
WoF Expiry:	17 May 2025	Odometer:	307,283 Kms	Good No:	26455325	Oil level	~			
VIN:	VSKCVAD40A0536857	Next Service:	0km	Service Histor	y: Yes	Smoke & fumes	~			
						Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
						Coolant condition	~			
						Performance	~			
Key:	R PT SC	-0	S P SC S P SC		s	Radiator / Hoses (visual)	~			
S = scratch						Transmission	Transmission			
D = dent S SC						Operation	~			
R = rust PT = paint defect						Noise	~			
C = crack						Clutch	~			
P = pin dent						CV joints	~			
*=decals SC QQ						Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs S SC S P SC S P SC S P SC						Performance				
Note: come defecte % blamiches may not be displayed in the diagram						Hand Brake	~			
body inspection comments							•	oftur))	
Rear Bumper moulding refit centre. Windscreen crack out of cva.						Tyres (lowest observed tread depth of tyres)				
איווינוגנופכון נומנא טערטו געמ.								5	mm	
						Right front		5	mm	
						Left rear		2	mm	
Conditions During Body Inspection:						Right rear 3 mm			mm	
Under Carriage & Under Report Inspection Comments						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension	1			
RWD. Surface rust underside.						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
Interior Comments						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	2001					Head lights	~			
Carpets	Poor					Tail lights		~		
						Indicators	~			
Panels	Poor					Dashboard warning lights	~			
Dest	Poor					Wipers (front & rear)	~			
Dashboa	iru					Window winder FL	~			
	_					Window winder FR	~			
<u>General Comments</u>						Window winder RL	~			
Radio display not working. Washer bottle cap missing.						Window winder RR	~			
Key cut not done properly key needs be halfway in to start also with fuel flap.						Rear view mirrors	~			
CD player not working. Condensation in L/H headlight.						Radio (basic test only)		~		
Reverse camera not working.						CD (basic test only)		~		
						Number of keys	1		•	
Road Conditions During Test Drive: Dry						Central locking	~			
,						Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~	
								1	1	
Inspected by: Imraan Bryant Date: 02 Dec 2024										

I have read and understood this condition guide.

Name:

Signature: