

Report ID: 26,455,484 3 Version: 12 Dec 2024 Created:

Make:	Mazda	Model:	Demio	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2014	Registration:	MEE361	Reg Expiry:	26 May 2025	Engine	1	I	1
WoF Expiry:	19 Dec 2025	Odometer:	109,032 Kms	Good No:	26455484	Oil level	~		<b></b>
VIN:	7AT0C12HX19164553	Next Service:	119000	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	r		+
	port is not a warranty	aration is made	for ago and miloago	Parts have not	been dismonthed or	Noise	V		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	D	-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission	ransmission		
D = dent	5 6/6			The		Operation	~		Т
R = rust PT = paint def				í In		Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		
* = decals	sc 916			- AL	ETTPS-	Wheel bearings	~		
SC = stone chips						Brakes	•		
W = significant scuffs S D W P P						Performance	~		
Noto come defecte 8 blamiches may not be displayed in the diagram						Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	-	oftyre	
						Right front		.5 .5	mm
						Left rear			
								.5	mm
Conditions During Body Inspection: Dry						Right rear	5.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare N/A			
	inage a onder bor	meemspeede	<u>on comments</u>			Suspension			1
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			T
Interior Comments						Operation	~		
						Electrical / Accessories	1		T
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		-
						Window winder FL	~		
Concert						Window winder FR	~		
<u>General Comments</u>					Window winder RL	~			
Has a tyre repair/inflation kit,no spare wheel						Window winder RR	~		
Drives well						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Janine Bell						Date: 10 Dec 2024			
Inspected by: Janine Bell Date: 10 Dec 2024									
I have read and understood this condition guide. Name:									