

Report ID: 26,455,581 2 Version: 13 Dec 2024 Created:

Make:	Mazda	Model:	CX-5	Body Style:	SUV		Pass	Fail	N/A
Year:	2021		NHQ754	Reg Expiry:	17 Feb 2025	Engine			
WoF Expiry:		Odometer:	91,399 Kms	Good No:	26455581	Oil level	~		
VIN:	JM0KF4WLA00418408	Next Service:	-	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		с I II			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:		-0	LS	-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust D PT D S						Operation	Operation		
R = rust PT = paint def				\prod		Noise	~		
C = crack				+		Clutch			~
P = pin dent	HIG				세비	CV joints	~		
* = decals	s 916			- No	ELLA S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs	$- \varnothing$				Performance	~		
Dealertee		Note: son	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	-	of tyres	5)
									mm
						Right front	5.0	-	mm
						Left rear	5.5		mm
Conditions During Body Inspection: Dry						Right rear	5.5 mm		
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Fuel						Suspension performance	~		
Fwd						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~	-+	
						Wipers (front & rear)	~	-+	
Dashboa	ird Good					Window winder FL	~	-+	
	I					Window winder FR	~	-+	
General Comments					Window winder RL	~			
Under engine cover broken,						Window winder RR	~	-+	
	· · · · · · ,					Rear view mirrors	~		
						Radio (basic test only)	~	-+	
						CD (basic test only)			~
						Number of keys	2	1	
Road Conditions During Test Drive: Dry						Central locking	~		
	Sectors During 103					Remote locking	~	-+	
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~	-+	
						-			
Inspected by: Marlon Espena Date: 02 Dec 2024									

I have read and understood this condition guide.

Name:

Signature: