

Basic Vehicle Condition Guide

Report ID: 26,457,186


3 Version:

12 Dec 2024 Created:

Make: Model: Mitsubishi Triton **Body Style:** Utility Year: 2019 Registration: MLZ624 Reg Expiry: 10 Feb 2025 **Odometer:** WoF Expiry: 23 Dec 2024 107,806 Kms **Good No:** 26457186 VIN: MMAJLKK10LH003714 Next Service: 120,000kms Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chip in windscreen CVA. Tonneau cover tear Driver's seat tear. Left rear seat small tear. Driver's door seal tear. Right rear door seal.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Rear wheel drive.

| Interior Comments | | | |
|-------------------|------|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Takaya Murayama Inspected by:

| Create | a: 12 | z Dec z | .024 | |
|------------------------------|---------------------------------------|---------|------|--|
| | Pass | Fail | N/A | |
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | ~ | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | ~ | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | 1 | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread | l depth | of tyre | es) | |
| Left front | 4 | .0 | mm | |
| Right front | 6 | .0 | mm | |
| Left rear | 8 | .0 | mm | |
| Right rear | 8 | .0 | mm | |
| Spare | | Yes | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation | ~ | | | |
| Electrical / Accessories | | | 1 | |
| Head lights | ~ | | | |
| Tail lights | | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | \(\triangle \) | | | |
| Wipers (front & rear) | | | | |
| Window winder FL | > > > > > > > > > > > > > > > > > > > | | | |
| Window winder FR | ~ | | | |
| Window winder RL | ~ | | | |
| Window winder RR | ~ | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 2 | | | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Cat Navy (basis tast amb) | | | ., | |

Sat. Nav. (basic test only)

Date:

03 Dec 2024

Reversing camera

I have read and understood this condition guide. Name: Signature: