

Report ID: 26,458,499 4 Version: 12 Dec 2024 Created:

NA - I-		M - 1 !				1		- ··	
Make:	Mitsubishi	Model:	Outlander	Body Style:	Wagon	F u sin s	Pass	Fail	N/A
Year: WoF Funimu	2010	-	PBL101	Reg Expiry:	12 Jan 2025	Engine			
		Odometer:	186,357 Kms	Good No:	26458499	Oil level	~		──
VIN:	7AT0CJ3MX21405865	Next Service:	141,863 Kms	Service Histor	y: No	Smoke & fumes	~		
Note: This re	port is not a warranty					Performance	~		<u> </u>
This report is	a guide only. Conside					Noise	~		
	sting undertaken. The v nical inspection prior to					Cooling System			
	· ·		-			Coolant condition	~		<u> </u>
Key:			D			Performance	~		<u> </u>
S = scratch	~	\sim (O)		5(O)-	\checkmark	Radiator / Hoses (visual)	~		
D = dent					SD SC W	Transmission		1	
R = rust					HIV	Operation	~		<u> </u>
PT = paint defe	ect N					Noise	~		
C = crack						Clutch			~
P = pin dent	sc dk				7HHs	CV joints	~		
* = decals SC = stone chi		20		70	SC SC	Wheel bearings	~		
W = significant	t scuffs	<u> (</u> 0)		=(Q)	\sim	Brakes			
ii sigiiiicaii	W					Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishe	s may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
Front bumper loose on right side						Left front	ont 7.6 r		
						Right front	7	.5	mm
						Left rear	7	.6	mm
Conditions During Body Inspection: Dry						Right rear	7	.7	mm
			bly			Spare		Yes	
<u>Under Ca</u>	rriage & Under Bor	nnet Inspectio	on Comments			Suspension			
	ula a du fuenat na accorran y) <i>f</i> uonataluin on aluin				Suspension performance	~		1
rusty under	rbody front passenger &	s front ariver ariv	verseals			Steering performance	~		+
						Shock absorbers	~		
						Air Conditioning / Heater			<u> </u>
						Operation	~		
Interior Comments						Electrical / Accessories	•		<u> </u>
Seats	Good					Head lights	~		1
50015	9000					Tail lights	~		
Carpets	Good						~		
Damala							-		┼──
Panels	Good					Dashboard warning lights Wipers (front & rear)	~ ~		<u> </u>
Dashboa	rd Good					Window winder FL	-		──
							/		──
General (Comments					Window winder FR	~		
<u>General Comments</u> Right rear window winds itself half way down sometimes when closing window off master switch					Window winder RL	~			
Right rear w	vindow winds itself half	way down some	etimes when closing w	undow off master	switch	Window winder RR	<u> </u>	~	──
						Rear view mirrors	~		──
						Radio (basic test only)	~		──
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		<u> </u>
Engine	ming Machanism	T ime in 1.4	Chain			Remote locking	~		<u> </u>
	ming Mechanism:	Timing (V 1		Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected	d by: Hoani Saunders					Date: 05 Dec 20	24		

I have read and understood this condition guide.

Name:

Signature: