

Report ID: 26,458,596 5 Version: 12 Dec 2024 Created:

Make:	Volkswagen	Model:	Golf	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2013	Registration:	HAT984	Reg Expiry:	25 Jul 2025	Engine	•	-	
WoF Expiry:	18 Dec 2025	Odometer:	81,801 Kms	Good No:	26458596	Oil level	~		
VIN:	WVWZZZAUZEW011700	Next Service:	90,500kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	V		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	V		
Key:		-0		-01-		Radiator / Hoses (visual)	V		
S = scratch						Transmission			
D = dent R = rust SC W D D PT						Operation	~		
PT = paint defect						Noise	V		
C = crack						Clutch			~
P = pin dent						CV joints	~		
* = decals						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs P W						Performance	~		
Rody Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	Tyres (lowest observed tread depth of tyres)		
Rear bumper has paint crack around dent.									mm
						Right front	6	.5	mm
						Left rear	7	.0	mm
Conditions During Body Inspection: Dry						Right rear	7	.0	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
L						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
						Tail lights	V		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
							24		
Inspected by: Yuki Itohara Date: 05 Dec 2024									

I have read and understood this condition guide.

Name:

Signature: