

Report ID: 26,458,959 Version: 1 02 Dec 2024 Created:

Make:	Volvo	Model:	V60	Body Style:	Wagon		Pass	Fail	N/A
Year:	2011	<b>Registration:</b>	MRF124	Reg Expiry:	14 Jan 2025	Engine	1	L	I
WoF Expiry:	20 Mar 2025	Odometer:	88,750 Kms	Good No:	26458959	Oil level	~		
VIN:	YV1FW485BB1029405	Next Service:	94,000 kms	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional c	harge.	Coolant condition	~		
			DS		S	Performance	~		
Key:		=		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	s dir			10	HI Is	Operation	~		
PT = paint defe	ect NP					Noise		>	
C = crack				TTX,		Clutch			~
P = pin dent	HIP				2416	CV joints	~		
* = decals SC = stone chips						Wheel bearings	~		
W = significant scuffs						Brakes			
	S D W		S D	W	S D	Performance	~		
Body Insp	ection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Boot area seal torn						Tyres (lowest observed tread depth of tyres)			
Turbo oil leak Tyre mobility kit available						Left front	6 mm		mm
	ly Kit available					Right front	8	3	mm
						Left rear	8	3	mm
Conditions During Body Inspection: Dry						Right rear	7 mm		mm
						Spare	N/A		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Fwd Engine oil leak						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Average						Electrical / Accessories			
Seats	Weldge					Head lights	~		
Carpets	Good					Tail lights	~		
	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
General (	omments					Window winder FR	~		
General Comments Transmission and Engine noise						Window winder RL	~		
	, , , , , , , , , , , , , , , , , , ,					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	<b>v</b>		
						Number of keys	2		
Road Con	ditions During Test	: Drive:	Dry			Central locking	<b>v</b>		
Engine Tir	ning Mechanism:	Timing (	Chain			Remote locking	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			<b>v</b>
		IV				Reversing camera			~
Inspected by: Vasanthakumar Mayilswamy Date: 02 Dec 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....