

Report ID: 26,459,436 3 Version: 12 Dec 2024 Created:

Make:	Holden	Model:	Commodore	Body Style:	Sedan		Pass	Fail	N/A
Year:	2011	<b>Registration:</b>	FWL482	Reg Expiry:	17 Nov 2025	Engine	1		1
WoF Expiry:	21 Nov 2025	Odometer:	306,418 Kms	Good No:	26459436	Oil level	~		
VIN:	6G1EK5EV2BL533112	Next Service:	311828	Service Histor	<b>y:</b> No	Smoke & fumes	~		<u> </u>
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	nical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	SCW		SC P SC		S	Performance	~		
Key:		-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	SC A			710	S PT	Operation	~		
PT = paint def	ect NP				17111	Noise	~		
C = crack						Clutch			~
P = pin dent	s sc dl				74116	CV joints	~		
* = decals		10		10	SD SD	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significan	SC W		SC SC		SC	Performance	~		
Body Insi	pection Comments	Note: son	ne defects & blemishes	s may not be disp	played in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			ès)
						Left front	7.	.0	mm
						Right front	7.	.0	mm
						Left rear	7.	.0	mm
Conditions During Body Inspection: Dry						Right rear	7.0 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
2wd						Suspension performance	<		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpote	duita e a fla					Tail lights	~		
Carpets	anversho	or mat hole in it				Indicators	~		
Panels	Average					Dashboard warning lights	2		
Dashboa	ard					Wipers (front & rear)	~		
	ard Average					Window winder FL	~		
						Window winder FR	~		<u> </u>
General (	<u>Comments</u>					Window winder RL	~		<u> </u>
						Window winder RR	~		
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		<u> </u>
Engine Timing Mechanism: Timing Chain						Remote locking	~		
						Sat. Nav. (basic test only)			~
Evidence	or Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Uriah Pepene Date: 04 Dec 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....