

Basic Vehicle Condition Guide

Report ID: 26,460,132

Pass

V

~

2 Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Performance

Operation

Noise

Clutch

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Right front

Left rear

Right rear

Suspension

Operation

Head lights Tail lights Indicators

Shock absorbers Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL Window winder RR

Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Reversing camera

Sat. Nav. (basic test only)

Suspension performance Steering performance

Spare

Coolant condition

Radiator / Hoses (visual)

12 Dec 2024 Created:

Fail

N/A

~

1

1

mm

mm

mm

mm

8.0

8.0

5.0

5.0

1

/

/

/

~

1 1 1


~

Yes

Make: Model: Tesla Model Y **Body Style:** SUV Year: 2022 Registration: PLB859 **Reg Expiry:** 12 Sep 2025 WoF Expiry: **Odometer:** 12 Sep 2025 59,470 Kms **Good No:** 26460132 **Next Service:** LRWYHCFS2NC441492 VIN: **Service History:** No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Air conditioning and heating systems along with reverse camera and navigation work fine at inspection time

Dry

I have read and understood this condition guide.

Not Applicable Kms:

03 Dec 2024 Date:

Name:	 Signature:	

Road Conditions During Test Drive:				
Engine Timing Mechanism: Evidence of Cam Belt Replaceme	Unkno ent:			
Inspected by: Gary Adams				