

diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends	Cooling System	I	
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.	Coolant condition	~	
	Performance	~	
Key:	Radiator / Hoses (visual)	~	
S = scratch D = dent	Transmission	II	I
R = rust S SC D D S SC	Operation	~	
PT = paint defect	Noise	~	
C = crack	Clutch		~
P = pin dent	CV joints	~	
* = decals SSC QIQ	Wheel bearings	~	
SC = stone chips	Brakes		
W = significant scuffs S SC D W SC	Performance	~	
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram	Hand Brake	~	
body inspection comments	Tyres (lowest observed tread	depth of	tyres)
Minor stone chips in front screen.	Left front	6.0	mm
	Right front	6.0	mm
	Left rear	3.0	mm
Conditions During Body Inspection: Dry	Right rear	4.0	mm
	Spare	Y	es
Under Carriage & Under Bonnet Inspection Comments	Suspension		
	Suspension performance	~	
	Steering performance	~	
	Shock absorbers	~	
	Air Conditioning / Heater	II	
	Operation	~	
Interior Comments	Electrical / Accessories	I	
Seats Average	Head lights	~	
	Tail lights	~	
Carpets Average	Indicators	~	
Panels Average	Dashboard warning lights	~	
	Wipers (front & rear)	~	
Dashboard Average	Window winder FL	~	
	Window winder FR	~	
General Comments	Window winder RL	~	
Tailgate interior grab handle broken off	Window winder RR	~	
	Rear view mirrors	~	
	Radio (basic test only)	~	
	CD (basic test only)	~	
	Number of keys	2	1
Road Conditions During Test Drive: Dry	Central locking	~	
	Remote locking	~	
Engine Timing Mechanism: Timing Chain	Sat. Nav. (basic test only)	~	
Evidence of Cam Belt Replacement: Not Applicable Kms:	Reversing camera	~	
Inspected by: Gary Adams Date: 04 Dec 2024			

I have read and understood this condition guide.

Name:

Signature:

Report ID: 26,460,465 Version: 3 Created: 09 Jan 2025

Pass

V

V

V

V

Fail

N/A