

LRWYHCFS9NC45534; Next Service:

20 Sep 2025 26460607

Engine

Oil level

Noise

Smoke & fumes

Coolant condition

Performance

Performance

Left rear

Right rear

Suspension

Suspension performance

Steering performance

Air Conditioning / Heater

Radio (basic test only)

Shock absorbers

Spare

Service History: Yes

W

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends Cooling System a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

0

Key: Radiator / Hoses (visual) S = scratch Transmission D = dent S Operation R = rustNoise PT = paint defect C = crackClutch P = pin dent CV joints * = decals Wheel bearings SC = stone chips Brakes W = significant scuffs W Performance Note: some defects & blemishes may not be displayed in the diagram Hand Brake **Body Inspection Comments** Tyres (lowest observed tread depth of tyres) Left front **Right front**

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments Rear wheel drive

Interior Comments		Opera	ion	~	
		Electric	Electrical / Accessories		
Seats	Good	Head I	ghts	~	
Carpets	Good	Tail lig	hts	~	
		Indicat	ors	~	
Panels	Good	Dashb	oard warning lights	~	
Dashboard	Good	Wipers	(front & rear)	~	
		Windo	w winder FL	~	
		Windo	w winder FR	~	
General Comments		Windo	w winder RL	~	
		Windo	w winder RR	~	
		Rear vi	ew mirrors	~	

	CD (basic test only)		
	Number of keys	1	
Road Conditions During Test Drive: Wet	Central locking	~	
	Remote locking	~	
Engine Timing Mechanism: Unknown	Sat. Nav. (basic test only)	~	
Evidence of Cam Belt Replacement: Not Applicable Kms:	Beversing camera		

Xinghui Lin Inspected by:

05 Dec 2024 Date:

Report ID: 26,460,607 Version: 1 Created: 05 Dec 2024

Pass

V

V

V

~

V

3.5

3.5

3.5

3.5

V

V

~

N/A

Fail

N/A

V

V

~

V

V

~

V

1

~

mm

mm

mm

mm

V

I have read and understood this condition guide.

Name:

Signature: