

Report ID: 26,461,359 Version: 2 03 Dec 2024 Created:

Make:	Ford	Model:	Territory	Body Style:	SUV] [Pass	Fail	N/A
Year:	2005	Registration:	EJO641	Reg Expiry:	13 Jun 2025	Engine	1 4 3 3	1 an	
WoF Expiry:		Odometer:		Good No:	26461359	Oil level			1
VIN:	03 Mar 2025 6FPAAAJGAT5K32058		239,936 Kms				~		
	6FPAAAJGA15K32058	Next Service:		Service History	/: No	Smoke & fumes	~		
Note: This re	port is not a warranty					Performance	~		<u> </u>
	s a guide only. Conside					Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
			-			Coolant condition	~		
Key:	P SC		P SC S D		S D	Performance	~		
S = scratch	~	\sim (O)		5(O)-		Radiator / Hoses (visual)	~		
						Transmission			
R = rust	s c sc				HIL	Operation	~		
PT = paint def	ect N	1			PT SC R	Noise	~		
C = crack					PISCR	Clutch			~
P = pin dent	PT SC DE				74HL	CV joints	~		
* = decals		10		10	ED C	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w – signincan	S PT W		D PT SC		R	Performance	~		
Body Insi	pection Comments	Note: son	ne defects & blemishe	s may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Rear Tailgate Garnish Broken , Wheel centre caps missing x 3 , Engine Bay surface rust , Bonnet stays need						Tyres (lowest observed tread depth of tyres)			
Regas ,						Left front	8	.0	mm
						Right front	7	.0	mm
						Left rear		.0	mm
Conditions During Body Inspection: Dry						Right rear	7.0		mm
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Oil leak low	ver engine Area & Rear D	Diff Area , surface	rust on under body o	f Vehicle, oil seep	age upper Engine	Suspension performance	~		1
Area,	5			•	5 5	Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		<u> </u>
						Operation			1
Interior Comments						Electrical / Accessories	V		
	Poor					Head lights			1
Seats							~		
Carpets	Poor					Tail lights	~		
	Poor					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	Average					Wipers (front & rear)	~		<u> </u>
	-					Window winder FL	~		<u> </u>
Concert	Commerte					Window winder FR		~	<u> </u>
General	<u>Comments</u>					Window winder RL	~		<u> </u>
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry Central locking									
	-		•			Remote locking	~		
Engine Ti	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)	1		~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspecte	d by: Chris Buckley					Date: 03 Dec 20	24		

I have read and understood this condition guide.

Name:

Signature: