

Basic Vehicle Condition Guide

Report ID: 26,461,448


Version: 2

Created: 04 Dec 2024

Make: Model: Nissan Serena **Body Style:** Van Year: 2005 Registration: NFF37 Reg Expiry: 14 Dec 2024 WoF Expiry: **Odometer:** 26 Jul 2025 169,243 Kms **Good No:** 26461448 VIN: 7AT0DH3FX20025217 **Next Service:** 0km **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Surface rust on R/R&L/R door striker.

Rear bumper damaged. R/R tail light scratched.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

FWD.

| Interior Comments | | | |
|-------------------|------|--|--|
| Seats | Poor | | |
| Carpets | Good | | |
| Panels | Poor | | |
| Dashboard | Good | | |

General Comments

Front spot lights not working. Exhaust has rattle.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Imraan Bryant Date: 04 Dec 2024

Name:

| | Pass | Fail | N/A |
|------------------------------|--|---------|-----|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | ~ | | |
| Performance | \(\times \) | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | | 5 | mm |
| Right front | 4 | | mm |
| Left rear | - | 7 | mm |
| Right rear | 3 | 3 | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | ! | | - |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | ~ | | |
| Window winder FR | \(\times \) \(\t | | |
| Window winder RL | v | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 1 | | |
| Central locking | · | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | <u> </u> | | ~ |
| Reversing camera | ~ | | |
| eversing currieru | | | |

Signature: