

Report ID: 26,461,681 3 Version: 12 Dec 2024 Created:

Make:	Holden	Model:	Colorado	Body Style:	Utility][]	Pass	Fail	N/A
Year:	2019	Registration:	MLS805	Reg Expiry:	21 Dec 2024	Engine		1	
WoF Expiry:	27 Nov 2025	Odometer:	97,138 Kms	Good No:	26461681	Oil level	~		
VIN:	MMU148EK0LH617719	Next Service:	103000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	D		Р		S D	Performance	~		
Key:		-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent R = rust PT = paint defect						Transmission			
						Operation	~		
						Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		
" = decais						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
P D SP						Performance	~		
Body Inst	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
Left taillight cracked Ute tray cover not covering properly						Left front	nt 6.0 m		
						Right front	7	.0	mm
						Left rear	7	.0	mm
Conditions During Body Inspection: Dry						Right rear	7.0 mm		
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension	-		
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments					Electrical / Accessories				
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
	0000					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
Comoral (Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
Partial service history						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Tir	ning Mechanism:	Timing				Remote locking	~		
						Sat. Nav. (basic test only)			~
Lvidence			lot Applicable	11115.		Reversing camera	~		
Inspected	d by: Sione Mae					Date: 03 Dec 20	24		

I have read and understood this condition guide.

Name:

Signature: