

Basic Vehicle Condition Guide

Report ID: 26,461,718


2 Version:

19 Dec 2024 Created:

Make: Model: Volkswagen Tiguan **Body Style:** Wagon Year: 2009 Registration: LRM957 Reg Expiry: 17 Jun 2024 **Odometer:** WoF Expiry: 19 Dec 2025 117,992 Kms **Good No:** 26461718 VIN: WVGZZZ5NZ9W078318 Next Service: 125,000 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Minor stone chips in front screen

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | | | |
|-------------------|---------|--|--|
| Seats | Average | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | Average | | |

General Comments

Dash cluster has screen blemish.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

05 Dec 2024 **Gary Adams** Inspected by: Date:

| | Pass | Fail | N/A |
|------------------------------|--|---------|----------|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | VVV | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | • | • | • |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | • | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | V | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | depth | of tyre | es) |
| Left front | 3 | .0 | mm |
| Right front | 3.0 | | mm |
| Left rear | 4.0 | | mm |
| Right rear | 4.0 | | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | \(\times \) \(\t | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | ' | | |
| Window winder RR | V | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 2 | | |
| Central locking | • | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | ' |
| Reversing camera | | | |

I have read and understood this condition guide.

Name:

Signature: