

Basic Vehicle Condition Guide

Report ID: 26,462,320


Version: 2

Created: 12 Dec 2024

Make: Model: Suzuki Swift **Body Style:** Hatchback Year: 2022 Registration: PFJ321 Reg Expiry: 18 Apr 2025 **WoF Expiry: Odometer:** 19 Apr 2025 23,133 Kms **Good No:** 26462320 VIN: JSAAZCA3S00547810 Next Service: 32,000 km Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Windscreen chip out of cva.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

FWD.

| Interior Comments | | | |
|-------------------|------|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

| C | <u></u> |
|---------|----------|
| uenerai | Comments |

Fault codes.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Imraan Bryant Date: 03 Dec 2024

Name:

| | Pass | Fail | N/A | | |
|------------------------------|--------------|---------|------|--|--|
| Engine | Pass | Ган | IN/A | | |
| Oil level | | | | | |
| Smoke & fumes | | | | | |
| Performance | \(\times \) | | | | |
| Noise | • | | | | |
| Cooling System | • | | | | |
| Coolant condition | | | | | |
| Performance | • | | | | |
| Radiator / Hoses (visual) | <i>v</i> | | | | |
| Transmission | V | | | | |
| Operation | ./ | | | | |
| Noise | •/ | | | | |
| Clutch | | | | | |
| CV joints | | | | | |
| Wheel bearings | • | | | | |
| Brakes | | | | | |
| Performance | · / | | | | |
| Hand Brake | <i>y</i> | | | | |
| Tyres (lowest observed tread | l denth | of tyre | 25) | | |
| Left front | I | .0 | mm | | |
| Right front | 7.0 | | mm | | |
| Left rear | 6.0 | | mm | | |
| Right rear | 7.0 | | mm | | |
| Spare | | N/A | | | |
| Suspension | | | | | |
| Suspension performance | ~ | | | | |
| Steering performance | ~ | | | | |
| Shock absorbers | ~ | | | | |
| Air Conditioning / Heater | <u> </u> | | | | |
| Operation | ~ | | | | |
| Electrical / Accessories | | | | | |
| Head lights | ~ | | | | |
| Tail lights | ~ | | | | |
| Indicators | v | | | | |
| Dashboard warning lights | ~ | | | | |
| Wipers (front & rear) | ~ | | | | |
| Window winder FL | ~ | | | | |
| Window winder FR | ~ | | | | |
| Window winder RL | ~ | | | | |
| Window winder RR | ~ | | | | |
| Rear view mirrors | ~ | | | | |
| Radio (basic test only) | ~ | | | | |
| CD (basic test only) | | | ~ | | |
| Number of keys | 1 | | | | |
| Central locking | ~ | | | | |
| Remote locking | ~ | | | | |
| Sat. Nav. (basic test only) | | | ~ | | |
| Reversing camera | ~ | | | | |
| | | | | | |

Signature: