

Basic Vehicle Condition Guide

Report ID: 26,463,405


Version: 4

Created: 12 Dec 2024

Make: Model: Suzuki Escudo **Body Style:** Wagon Year: 2006 Registration: JEF493 Reg Expiry: 21 Jun 2025 **WoF Expiry: Odometer:** 16 Apr 2025 158,583 Kms **Good No:** 26463405 VIN: 7AT0GK4MX1510198 Next Service: 166000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Average			
Carpets	Average			
Panels	Average			
Dashboard	Average			

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Sione Mae Date: 06 Dec 2024

	Pass	Fail	N/A	
Engine		•		
Oil level	~			
Smoke & fumes	\(\times \)			
Performance	~			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	V			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes		•		
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread	d depth	of tyre	es)	
Left front	7	.0	mm	
Right front	7.0		mm	
Left rear	8.0		mm	
Right rear	7.0		mm	
Spare		Yes		
Suspension	•			
Suspension performance	~			
Steering performance	V V			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	~			
Wipers (front & rear)	~			
Window winder FL	~			
Window winder FR	V V V V V V V V V V V V V V V V V V V			
Window winder RL	~			
Window winder RR	~			
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	1	-	-	
Central locking	~			
Remote locking	~			
Sat. Nav. (basic test only)			~	
Reversing camera			~	

I have read and understood this condition guide.

Name:

Signature: