

Report ID: 26,463,802 Version: 1 10 Dec 2024 Created:

Make:	Mazda	Model:	Atenza	Body Style:	Sedan		Pass	Fail	N/A
Year:	2006	Registration:	LWY920	Reg Expiry:	10 Mar 2025	Engine	1		
WoF Expiry:	29 Nov 2024	Odometer:	185,975 Kms	Good No:	26463802	Oil level	~		
VIN:	7AT0C139X18404454	Next Service:	187,000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:	SRSC	-0	SRSC SRP	-01-	SP	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust PT = paint defect						Operation	~		
						Noise	~		
C = crack					S R SC	Clutch	-		~
P = pin dent	HID				7414	CV joints	~		-
* = decals SRSC 919 SDRPT						Wheel bearings	~		
SC = stone chips						Brakes	•		
W = significant scuffs S R SC S C P SC S R PT P S PT						Performance	~		
		Note: som	e defects & blemishes	may not be disc	played in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	-	oftvre	
Headlights Faded Minor Stone ChipsWindscreen									
Left Mirror Cover Cracked						Right front			mm
						Left rear		.5	mm
								.5	-
Conditions During Body Inspection: Dry						Right rear 2.5 mm Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
Power Steering Seepage - Expected for Age & Mileage									
1 ower siee		a for Age & Milea	ge			Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation		~	
Stains						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
Concert						Window winder FR	~		
General Comments					Window winder RL	~			
Grinding & Whining from Power Steering Pump Vibration from Rear						Window winder RR	~		
Passenger Grab Handle Broken					Rear view mirrors	~			
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Samuel Weir Date: 10 Dec 2024									

I have read and understood this condition guide.

Name:

Signature: