

Report ID: 26,466,555 2 Version: 12 Dec 2024 Created:

Make:	Volkswagen	Model:	Polo	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2006	Registration:	DLT432	Reg Expiry:	15 Jun 2025	Engine	I		
WoF Expiry:	09 Dec 2025	Odometer:	145,722 Kms	Good No:	26466555	Oil level	~		
VIN:	WVWZZZ9NZ6Y143058	Next Service:	155700	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
	SCW		PT SC D			Performance	~		
Key:		-0		-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust				715	PT W	Operation	~		
PT = paint def	ect NP			$\left[\left(\right) \right]$		Noise	~		
C = crack						Clutch	~		
P = pin dent	sc dle				74116	CV joints	~		
* = decals				To .	ED PT	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs D S D PT PT P W S P						Performance	~		
Body Inc	action Commonts	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
						Left front	4.	.0	mm
						Right front	3.	.9	mm
						Left rear	4.	.0	mm
Conditions During Body Inspection: Dry						Right rear	4.	.3	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			<u> </u>
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		•
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
Inspecte	d by: Hoani Saunders					Date: 06 Dec 20	24		

I have read and understood this condition guide.

Name:

Signature: