

Report ID: 26,467,256 3 Version: 12 Dec 2024 Created:

Make:	Ford	Model:	Fiesta	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2012	Registration:	GJY862	Reg Expiry:	30 Aug 2025	Engine	I		1
WoF Expiry:	31 Jul 2025	Odometer:	133,674 Kms	Good No:	26467256	Oil level	~		
VIN:	MNBJXXARJJBP78028	Next Service:	151,000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		+
Key:	SRSC	-0	S S	-161-	R SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s sc dl			The	S SC	Operation	~		
R = rust				\int	JHIH	Noise	~		
PT = paint defect C = crack						Clutch	•		~
P = pin dent						CV joints	~		
* = decals SRSC 919						Wheel bearings	~		
SC = stone chips						Brakes	V		
W = significant scuffs SSC S S						Performance			
Noto: come defecte % blamiches may not be displayed in the displayer						Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							•	ofture	
No spare wheel provided by manufacturer but emergency tire inflation device is in the boot. Headlights						Tyres (lowest observed tread depth of tyres)			
faded						Left front	5.		mm
						Right front	5.		mm
						Left rear	6.		mm
Conditions During Body Inspection: Dry						Right rear	6.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare N/A			
onder carnage & onder bonnet inspection comments						Suspension			
Tested batt	ery and passed. Runs or	n 95 octane fuel				Suspension performance	~		<u> </u>
						Steering performance	~		\square
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
	Avelage					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	ard Assess					Wipers (front & rear)	~		
Dastibud	ard Average					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
Air conditioning and heating systems work fine at inspection time						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	<		
						CD (basic test only)	<		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
	-					Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	'es	Kms: 12	7,000	Reversing camera			~
Inspected by: Gary Adams Date: 09 Dec 2024									
I have read and understood this condition guide. Name:									