

Basic Vehicle Condition Guide

Report ID: 26,467,646


5 Version:

12 Dec 2024 Created:

Make: Model: Mitsubishi Triton **Body Style:** Utility Year: 2017 Registration: KMY429 Reg Expiry: 19 Jan 2025 **Odometer:** WoF Expiry: 19 Apr 2025 332,562 Kms **Good No:** 26467646 VIN: MMAJYKK10HH007641 **Next Service:** 337000 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	drivers seat torn			
Carpets	Poor			
Panels	Poor			
Dashboard	Poor			

General Comments

Air conditioning not working

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Kilipati Mae 05 Dec 2024 Inspected by:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\triangle \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	V		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	7	.0	mm
Right front	7	.0	mm
Left rear	6	.0	mm
Right rear	6	.0	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation		~	
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	•		
Window winder FL	V V V V V V V V V V V V V V V V V V V		
Window winder FR	<i>'</i>		
Window winder RL	•		
Window winder RR	•		
Rear view mirrors			
Radio (basic test only)	<i>'</i>		
CD (basic test only)	1		
Number of keys	1		
Central locking	<i>V</i>		
Remote locking	· ·		
Sat. Nav. (basic test only)			'
Reversing camera			

I have read and understood this condition guide.

Name:			