

Report ID: 26,467,680 Version: 3 10 Dec 2024 Created:

| Make: | Holden | Model: | Colorado | Body Style: | Utility | | Pass | Fail | N/A |
|--|------------------------|-----------------|------------------------|---------------------------------|----------------------|---|--------|------|-----|
| Year: | 2019 | Registration: | MNA497 | Reg Expiry: | 26 Feb 2025 | Engine | | | |
| WoF Expiry: | | Odometer: | 79,606 Kms | Good No: | 26467680 | Oil level | ~ | | |
| VIN: | MMU148LK0LH62169 | Next Service: | 91000 | Service Histor | y: Yes | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | avation is made | for one and miles as | Dauta hava nat | heen discontined or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| | | | | | | Coolant condition | | | |
| | | | | | Р | Performance | ~ | | |
| Key: | | -0 | S P | -01- | | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent R = rust | | | | 715 | HIV | Operation | ~ | | |
| PT = paint defe | ect NP | FI | | $\left[\left(\right) \right]$ | | Noise | ~ | | |
| C = crack | | | | | D | Clutch | | | ~ |
| P = pin dent | HIG | | | | 74114 | CV joints | ~ | | |
| * = decals | DSC 91 | | | The second | | Wheel bearings | ~ | | |
| SC = stone chips W = significant scuffs | | | | | | Brakes | | | |
| vv = significan | s cuffs | | P P | | D | Performance | ~ | | |
| Body Insr | pection Comments | Note: son | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | ~ | | |
| Body Inspection Comments | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | | Left front | 3.0 | 0 | mm |
| | | | | | | Right front | 4.(| 0 | mm |
| | | | | | | Left rear | 3.0 | 0 | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 5.0 mm | | mm |
| | | | | | | Spare | Yes | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | 1 1 | | |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| | Good | | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| | torn steeri | na wheel | | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd | J | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| <u>General Comments</u> | | | | | | Window winder RL | ~ | | |
| Partial servi | ce history | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| L | | | | | | Number of keys | 2 | | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | |
| | | | · | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | ~ | | |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | ~ | | |
| Inspected by: Sione Mae Date: 07 Dec 2024 | | | | | | | | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: