

Report ID: 26,468,004 5 Version: 12 Dec 2024 Created:

Make:	Nissan	Model:	Murano	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2010	Registration:	MFE233	Reg Expiry:	24 Jan 2025	Engine			
WoF Expiry:	04 Jan 2025	Odometer:	234,684 Kms	Good No:	26468004	Oil level	~		
VIN:	7AT0DH74X19006216	Next Service:	237000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and ti	his can be arranged to	r an additional o	charge.	Coolant condition	~		
	SC					Performance	~		
Key:						Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust SSC S						Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack					SC	Clutch			~
P = pin dent	DSC DR				2414	CV joints	~		
						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w – significan	S					Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
R/F Fog lamp cracked ,						Left front	6.0 mm		mm
						Right front	6.0 m		mm
						Left rear	7.	.0	mm
Conditions During Body Inspection: Wet						Right rear	6.0 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Oil leak lower engine Area, surface rust rear suspension components.						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Comoto						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
					I	Window winder FR	~		
General Comments						Window winder RL	~		
.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
Inspected by: Chris Buckley Date: 05 Dec 2024									

I have read and understood this condition guide.

Name:

Signature: