

WoF Expiry:	14 Jul 2025	Odometer:	75,098 Kms	Good No:	26469048	Oil level	~		
VIN:	KMHS281KSMU38162	Next Service:		Service History	No No	Smoke & fumes	~		
NI / 1911						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Noise	~		
						Cooling System			
						Coolant condition	~		
	S		S P S			Performance	~		
Key:	L'IL	-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent R = rust						Transmission			
						Operation	~		
PT = paint defect					Noise	~			
C = crack P = pin dent * = decals SC = stone chips W = significant scuffs						Clutch		~	
						CV joints	~		
						Wheel bearings	~		
						Brakes			
w – significan	S		S P S P		S P	Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishes	s may not be displ	ayed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed trea	d depth of	tyres)	
						Left front	3	mm	
						Right front	3.8	mm	
						Left rear	4	mm	
Conditior	ns During Body Ins	pection:	Dry			Right rear	4	mm	
···· 5··· 5··						Spare	Ye	es	
Under Carriage & Under Bonnet Inspection Comments						Suspension	•		
All wheel drive.						Suspension performance	~		
Front tyres	wear.					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater		•	
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Comoto	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	Good					Wipers (front & rear)	~		
Dashboa	ru					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Service overdue.					Window winder RR	~			
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)		~	
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
,						Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)	~		
						Reversing camera	~		
Inspected by: Takaya Murayama Date: 05 Dec 2024									

I have read and understood this condition guide.

Name:

Signature:

Report ID: 26,469,048

1

Pass

05 Dec 2024

Fail

N/A

Version:

Created:

Engine