

Basic Vehicle Condition Guide

Report ID: 26,469,421


Version: 5

Created: 12 Dec 2024

Make: Model: Peugeot 407 **Body Style:** Sports Car Year: 2007 Registration: CAW795 Reg Expiry: 30 Nov 2025 WoF Expiry: **Odometer: Good No:** 09 May 2025 137,602 Kms 26469421 VIN: VF36JUHZJ21489008 Next Service: 147600 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Damage to engine oil sump

<u>Interior Comments</u>		
Seats	Average	
Carpets	Average	
Panels	Average	
Dashboard	Average	

General Comments

Coolant Leak

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Kms:

Pass	Fail	N/A
~		
~		
~		
~		
	~	
~		
	~	
	•	•
~		
~		
		~
~		
~		
	ı	
~		
~		
d depth	of tyre	<u></u>
6	.0	mm
6	.0	mm
6.0 mm		
6.0 m		mm
	Yes	
~		
~		
~		
	ļ	
v		
~		
<i>v</i>		
V V		
V V V		
1		
<i>V</i>		
<i>V</i>		
V V V		
V V V		
V V V		
V V V V V		
V V V V V		
V V V V V		
V V V V V V		
V V V V V V		
V V V V V V		
	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ	V

Reversing camera

1

Signature:

Inspected by: Sione Mae Date: 06 Dec 2024

Name: