

Report ID: 26,470,860 4 Version: 12 Dec 2024 Created:

Make:	Nissan	Model:	Elgrand	Body Style:	Wagon		Pass	Fail	N/A
Year:	2010	<b>Registration:</b>	PDY1	Reg Expiry:	10 Dec 2024	Engine	1		1
WoF Expiry:	22 Oct 2025	Odometer:	90,073 Kms	Good No:	26470860	Oil level	~		
VIN:	7AT0DH6MX21001135	Next Service:	100,000kms	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
	S		S SPW		S	Performance	~		
Key:	L'	-0	3 SFW			Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	S SC			715	HIL SP	Operation	~		
PT = paint defe		r I		$\left( \left  \left( \right) \right\rangle \right)$		Noise	~		
C = crack					S SC	Clutch			~
P = pin dent	HIC				74114	CV joints	~		
* = decals	SPSC 916			-July		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S S S S S S S S S S						Performance	~		
Rody Inspection Commenter Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyre			es)
						Left front 4.0			
						Right front	4.		mm
						Left rear	5.		mm
Conditions During Body Inspection: Dry						Right rear		.2	mm
Conditions During Body Inspection: Dry						Spare N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation 🖌			
Interior Comments						Electrical / Accessories	•		<u> </u>
Seats Average						Head lights	~		
	Avelage					Tail lights	~		+
Carpets	Good					Indicators	~		+
Panels	Good					Dashboard warning lights	~		+
						Wipers (front & rear)	~		+
Dashboa	rd Average					Window winder FL	~		+
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		+
Seven small cuts in back panel on rear seats. Dashboard vinyl starting to crack on right side.						Window winder RR	~		+
Jeven smar		cui scuts. Dusilb	sala miyi starting to t			Rear view mirrors	~		+
						Radio (basic test only)	~		+
						CD (basic test only)	~		+
						Number of keys	2		1
Road Conditions During Test Drive: Dry						Central locking	~		
Road Conditions During Test Drive: Dry						Remote locking	~		+
Engine Tir	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		-
	•	•							
Inspected by: Jason Young Date: 09 Dec 20.							24		
I have read and understood this condition guide. Name:									