

<b>Make:</b> Nissan	<b>Model:</b> Navara	<b>Body Style:</b> Utility
<b>Year:</b> 2014	<b>Registration:</b> JSE898	<b>Reg Expiry:</b> 30 Sep 2024
<b>WoF Expiry:</b> 31 Jan 2025	<b>Odometer:</b> 178,621 Kms	<b>Good No:</b> 26471886
<b>VIN:</b> MNTVCGD40A0004657	<b>Next Service:</b> 123,257	<b>Service History:</b> No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**  
 S = scratch  
 D = dent  
 R = rust  
 PT = paint defect  
 C = crack  
 P = pin dent  
 \* = decals  
 SC = stone chips  
 W = significant scuffs

**Body Inspection Comments** Note: some defects & blemishes may not be displayed in the diagram

Headlamps cloudy, Stone chips in windscreen

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments**

Rear wheel drive, Oil leak from back of head, Oil leak from injector pump, Green wiring hanging from under front, Battery insecure, Engine oil over full

**Interior Comments**

Seats	Average
Carpets	Average
Panels	Good
Dashboard	Good

**General Comments**

Drivers seat base foam collapsed, Seats stained, Rear interior light not working, Exposed wiring in LH/F foot well, Door open light stays on dash, Interior light stays on, Wipers need replacing, Carpets stained, Excessive black smoke under acceleration, Exhaust manifold leaking.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain  
 Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A
<b>Engine</b>			
Oil level		✓	
Smoke & fumes		✓	
Performance	✓		
Noise		✓	
<b>Cooling System</b>			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints			✓
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	4	mm	
Right front	5	mm	
Left rear	5	mm	
Right rear	4	mm	
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)		✓	
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. Nav. (basic test only)			✓
Reversing camera			✓

Inspected by: Andre Richardson Date: 20 Dec 2024

I have read and understood this condition guide. Name: ..... Signature: .....