

Report ID: 26,472,044 4 Version: 12 Dec 2024 Created:

Make:	Subaru	Model:	Legacy	Body Style:	Wagon		Pass	Fail	N/A
Year:	2011	Registration:	GBD946	Reg Expiry:	21 Nov 2025	Engine			L
WoF Expiry:	07 Dec 2025	Odometer:	159,000 Kms	Good No:	26472044	Oil level	~		
VIN:	JF1BR9K92BG026742	Next Service:	168,800	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for ago and miloago	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
	C C C W	M/				Performance	~		
Key:	s sc w	<u>~</u> ⊘	S P SC W S P W		/ SW	Radiator / Hoses (visual)	~		
S = scratch						Transmission			L
D = dent	sscw 616			The	SDW	Operation	~		
R = rust PT = paint def				r In	JHIA	Noise	~		
C = crack				+	SC	Clutch	•		~
P = pin dent	Ho					CV joints	~		
* = decals	PSC PSC				EIP SW	Wheel bearings	~		<u> </u>
SC = stone chips						Brakes			
W = significant scuffs S SC W S W S SC W S P SC W S P SC W S P W						Performance	~		
		Note: son			laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							•	ofter	
Headlamps cloudy,						Tyres (lowest observed tread depth of tyres)			
						Left front	8.		mm
						Right front	8.		mm
						Left rear	8.	-	mm
Conditions During Body Inspection: Dry						Right rear	8.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
onder camage & onder bonnet inspection comments						Suspension			
	rive, Rear differential m	ount rusty, Front	subframe rusty, LH ro	cker cover leakin	g, Rear main	Suspension performance	~		
leaking						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater	1 1		
Interior Comments						Operation	~		
						Electrical / Accessories			·
Seats	Good					Head lights	~		<u> </u>
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Cood					Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General (<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~
Increased by Andre Pichardson						Date: 06 Dec 2024			
Inspected by: Andre Richardson Date: 06 Dec 20									
I have read	and understood th	is condition c	uide. Name:			Signature:			