

Report ID: 26,472,689 Version: 1 20 Dec 2024 Created:

Make:	Audi	Model:	A3	Body Style:	Wagon		Pass	Fail	N/A
Year:	2007		KLG258	Reg Expiry:	06 Sep 2025	Engine		L	.1
WoF Expiry:		Odometer:	102,009 Kms	Good No:	26472689	Oil level	~		
VIN:	WAUZZZ8P47A099586	Next Service:	0	Service Histor	<b>y:</b> No	Smoke & fumes	~		
					-	Performance	~		
	port is not a warranty		for and milaan	Darte have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	o purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		1
						Performance	~		
Key:	SC	-0	SD SD	-161-	SD	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	S SC			ZIS	HIL S	Operation	~		1
R = rust PT = paint def				$\left( \left  \right\rangle \right)$		Noise	~		
C = crack				+	S SC	Clutch			~
P = pin dent	HIS				74114	CV joints	~		<u> </u>
* = decals	s sc 916			- No	ALC S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs SC	$\neg \otimes$	S SC S SC		S SC	Performance	~		1
Podylog	action Commont	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		<u> </u>
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			es)
						Left front	2.0 mn		
						Right front	2	.1	mm
						Left rear	6	.4	mm
Conditions During Body Inspection: Dry						Right rear	7	.5	mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Otherster	**					Suspension performance	~		1
CV boot spl	п					Steering performance	~		
						Shock absorbers	~		<u> </u>
						Air Conditioning / Heater			1
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
						Tail lights	~		
Carpets	Average					Indicators	~		1
Panels	Average					Dashboard warning lights	~		1
						Wipers (front & rear)	~	<u></u>	1
Dashboa	rd Average					Window winder FL	~		1
						Window winder FR	~		1
General Comments						Window winder RL	~		
Drives okay	r, needs a service					Window winder RR	~		1
, 						Rear view mirrors	~		1
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		•
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera	~		
							24		<u> </u>
Inspecte	d by: Donovan Mata	rð				Date: 06 Dec 20	24		

I have read and understood this condition guide.

Name: .....

Signature: .....