

Report ID: 26,472,731 2 Version: 20 Dec 2024 Created:

Make:	Toyota	Model:	Porte	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2007	Registration:	NMB59	Reg Expiry:	30 Jun 2025	Engine			
WoF Expiry:	14 Nov 2025	Odometer:	155,589 Kms	Good No:	26472731	Oil level	~		
VIN:	7AT0H64WX17025009	Next Service:	165000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
	P SC S		S D		S SC	Performance	~		
Key:		-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	S SC			710	SDC	Operation	~		
PT = paint defe	ect NP	1 II				Noise	~		
C = crack					S PT SC	Clutch			~
P = pin dent	S PT SC				2416	CV joints	~		
						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant	S S		S		S D	Performance	~		
Body Insr	ection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
Front bumper screwed in both front ends,					Left front	eft front 2.5 mr			
						Right front	3.7 mm		mm
						Left rear	4.	.3	mm
Conditions During Body Inspection: Dry						Right rear	4.2 mm		
					Spare N/A				
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
Shoc						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	itioning / Heater		
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	wear,stain	ed ,				Head lights	~		
Carpote						Tail lights	~		
Carpets	wear,minc	or stains ,				Indicators	۲		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd 4					Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
						Window winder FR	۲		
<u>General Comments</u>						Window winder RL			~
Drives okay	, Fresh Service					Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	۲		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
Inspected by: Donovan Matara Date: 06 Dec 2024									

I have read and understood this condition guide.

Name:

Signature: