

Report ID: 26,473,046 3 Version: 19 Dec 2024 Created:

Make:	Hyundai	Model:	130	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2018	<b>Registration:</b>	LJG803	Reg Expiry:	21 May 2025	Engine			L
WoF Expiry:	03 Jul 2025	Odometer:	94,991 Kms	Good No:	26473046	Oil level	~		
VIN:	TMAH3515MJJ06243(	Next Service:	105500	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	charge.	Coolant condition	~		
	Р		PW PW		SP	Performance	~		
Key:		-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	PW			210	HIVS	Operation	~		
PT = paint def	ect NP				10111	Noise	~		
C = crack					R	Clutch			~
P = pin dent	P				24116	CV joints	~		
*= decais						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significan	P W		P P		S P	Performance	~		
Body Inst	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			es)
Fresh Cut & Polish!						Left front	3.	0	mm
						Right front	6.	0	mm
						Left rear	6.	0	mm
Conditions During Body Inspection: Dry						Right rear	6.0 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpote	Card					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Card					Wipers (front & rear)	~		
	rd Good					Window winder FL	~		
Canada						Window winder FR	~		
<u>General Comments</u>					Window winder RL	~			
Partial servi	ce history					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanicm: Timing Chain						Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
	oi Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Sione Mae Date: 06 Dec 2024									
Inspected by. Sione mac Date: 00 Dec 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....