

## **Basic Vehicle Condition Guide**

Report ID: 26,473,344

Pass

Version:

Engine

17 Dec 2024 Created:


Fail

N/A

Make: Model: Holden Colorado **Body Style:** Utility Year: 2013 Registration: HBS325 Reg Expiry: 26 Mar 2025 **Odometer:** Good No: WoF Expiry: 11 Jan 2025 179,863 Kms 26473344 **Next Service:** VIN: MMU148CH0DH684309 189,871 Kms Service History:

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Right wing mirror indicator lens cracked. Stone chip on windscreen

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

<u>Interior Comments</u>				
Seats	Average			
Carpets	Average			
Panels	Average			
Dashboard	Good			

## **General Comments**

Inspected by:

Remote key blade not folding. Steering wheel worn.

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism:** Cambelt

**Evidence of Cam Belt Replacement:** No

Kms:

Oil level	~			
Smoke & fumes	~			
Performance	~			
Noise	\( \triangle \)			
Cooling System	•	•		
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission		•		
Operation	~			
Noise	<b>V</b>			
Clutch	~			
CV joints			~	
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread	depth	of tyre	s)	
Left front	7	.0	mm	
Right front	7.0		mm	
Left rear	6.0		mm	
Right rear	6.0 mm		mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	~			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \			
Wipers (front & rear)	~			
Window winder FL	~			
Window winder FR	~			
Window winder RL	~			
Window winder RR	V			
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	1			
Central locking	~			
Remote locking	~			
Sat. Nav. (basic test only)			1	

I have read and understood this condition guide.

Lewis Dolamore

Name: .....

Signature: .....

06 Dec 2024

1

Reversing camera