

Report ID: 26,473,681 4 Version: 12 Dec 2024 Created:

Make:	Mazda	Model:	Axela	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2007	Registration:	LPL229	Reg Expiry:	28 Feb 2025	Engine			
WoF Expiry:	30 Aug 2025	Odometer:	189,791 Kms	Good No:	26473681	Oil level	~		
VIN:	7AT0C13JX18308885	Next Service:	185,860	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
diagnostic tes	sting undertaken. The	vehicle has beer	n driven up to 50km/h	from cold. The	Vendor recommends	Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	S		S S		S	Performance	~		
Key:		-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust						Operation 🖌			
PT = paint defe		r I		$\left(\left \left(\right) \right\rangle \right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	ssc dP				74116	CV joints	~		
* = decals				To .		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant scutts S PT SC SC S S						Performance	~		
Body Incr	oction Commonts	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
						Left front 2.9 mr			mm
						Right front	4	.0	mm
						Left rear	2	.5	mm
Conditions During Body Inspection: Dry						Right rear	5.7 mm		mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Encine eile						Suspension performance	~		
Engine oil se	eepage					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	I				J	Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1	l	I
Road Con	Central locking								
Road Conditions During Test Drive: Dry Central locking Remote locking Remote locking							~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)							-		~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
	-								L *
Inspected by: Kyle Kelly Date: 08 Dec 2024									

I have read and understood this condition guide.

Name:

Signature: