

Report ID: 26,474,642 4 Version: 12 Dec 2024 Created:

Make:	Honda	Model:	Stream	Body Style:	Wagon			Pass	Fail	N/A
Year:	2007	Registration: KGY462 Reg Expiry: 17 Apr 2025				Engine	2			
WoF Expiry:	12 Aug 2025	Odometer:	neter: 171,493 Kms Good No: 26474642			Oil le	vel	~		
VIN:	7AT08GADX1601526(	Next Service:		Service Histor	<b>y:</b> No	Smol	ke & fumes	~		
						Perfc	ormance	~		
	port is not a warranty	aration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	5	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Coolant condition			
	S SC W		SC W W		SP	Perfo	ormance	~		
Key:	ISSC [W	-0	SC W W	$\square$	SP	Radia	ator / Hoses (visual)	~		
S = scratch						Transr	Transmission			
D = dent R = rust SC W D D W W						Oper	Operation			
PT = paint defe				$\prod$		Noise		~	~	
C = crack				$+ \vee$	S	Cluto			•	~
P = pin dent	HIC				세비	CV jo	ints	~		-
* = decals SC 919 S						·	Wheel bearings			
SC = stone chips						Wheel bearings				
W = significant scuffs S SC W P SC W W P W						Perfc	~			
		Note: som	ne defects & blemishes	mav not be disp	laved in the diagram		Brake	~		
Body Insp	pection Comments			,,			lowest observed tread	-	of tyre	) ()
Windscreen stone chip not in CVA										 mm
							Right front			
						Left rear				
Conditions Duving Rody lagranticut						Right rear		4.0 mm 4.0 mm		mm
Conditions During Body Inspection: Dry						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						-	ension performance	~		
						· · ·	ring performance	~		
							k absorbers	~		
						Air Conditioning / Heater				
Interior Comments						Operation 🖌				
						Head lights				
Seats	Average					Tail li	5	~		
Carpets	drivers sid	e torn				Indic	5	~		
Panels	Average						board warning lights ers (front & rear)	<b>v</b>		
Dashboa	rd Average					· ·	low winder FL	レ レ		
	_						low winder FL	<i>v</i> <i>v</i>		
General (	Comments						low winder FR			
							low winder RL	<b>v</b>		
Noisy trans	mission						view mirrors	~ ~		
							b (basic test only)	~		
								~		
							CD (basic test only)			
Read Conditions During Test Driver							Number of keys 1 Central locking 🖌			
Road Conditions During Test Drive: Dry							ote locking	~		
Engine Timing Mechanism: Timing Chain							-			<b>v</b>
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)				~
						Reve	rsing camera	~		
Inspected by: Sione Mae Date: 07 Dec 2024										

I have read and understood this condition guide.

Name: .....

Signature: .....