

Report ID: 26,475,042 4 Version: 12 Dec 2024 Created:

Make:	BMW	Model:	X3	Body Style:	Wagon		Pass	Fail	N/A
Year:	2005	Registration:	LBS594	Reg Expiry:	11 Jun 2025	Engine	1	I	
WoF Expiry:	15 May 2025	Odometer:	147,477 Kms	Good No:	26475042	Oil level	~		
VIN:	WBAPA72050WB67548	Next Service:	154,561 Kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	S		S SDP		SP	Performance	~		
Key:	L'IL	-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
B = rust				710	HIVP	Operation	~		
PT = paint def	ect NP				70111	Noise	~		
C = crack					PT	Clutch			~
P = pin dent						CV joints	~		
*= decais						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S D S PT S						Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			es)
Stone chips in front windscreen						Left front	3.2 m		mm
All tyres starting to wear on inner edges						Right front	3.5 m		mm
						Left rear	2.4 m		mm
Conditions During Body Inspection: Dry						Right rear	3.0 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
Steering performance							~		
Shock a							~		
						Air Conditioning / Heater		1	
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Large rip o	on drivers seat				Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights		~	
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Air bag war	ning light on					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry Central locking							~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav									~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
Inspected by: Hoani Saunders Date: 09 Dec 2024									

I have read and understood this condition guide.

Name:

Signature: