

Basic Vehicle Condition Guide

Report ID: 26,475,088


Version: 2

Created: 12 Dec 2024

Make: Model: XC60 Volvo **Body Style:** Wagon Year: 2009 Registration: JTT924 Reg Expiry: 10 Apr 2025 WoF Expiry: **Odometer: Good No:** 05 Nov 2025 160,238 Kms 26475088 VIN: YV1DZ9956A2072435 Next Service: 175000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>		
Seats	Good	
Carpets	Good	
Panels	Good	
Dashboard	Average	

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Kilipati Mae Date: 09 Dec 2024

Pass	Fail	N/A
~		
~		
~		
~		
~		
~		
~		
~		
~		
		~
~		
~		
~		
~		
d depth	of tyre	es)
7.0		mm
7	.0	mm
5.0		mm
5.0		mm
	Yes	
•		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
/		
~		
~		
~		
~		
2		
~		
V		
V		~
	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ	マ

I have read and understood this condition guide.

Name:

Signature: