

Basic Vehicle Condition Guide

Report ID: 26,475,246


Version: 2

Created: 07 Jan 2025

Make: Model: Mazda Atenza **Body Style:** Hatchback Year: 2008 Registration: LZM347 Reg Expiry: 04 May 2025 **Odometer:** WoF Expiry: 27 Dec 2025 197,343 Kms **Good No:** 26475246 VIN: 7AT0C139X19103148 Next Service: 207000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

No underbody inspection Transmission issues

| <u>Interior Comments</u> | | | |
|--------------------------|--|--|--|
| Seats | wear | | |
| Carpets | wear | | |
| Panels | sunglasses holder broken and missing | | |
| Dashboard | wear steering wheel, scratches, cracks | | |

General Comments

Transmission issues

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Melissa Wilson Date: 07 Jan 2025

Name:

| | Pass | Fail | N/A |
|------------------------------|--------------|---------|----------|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | ~ | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | 2S) |
| Left front | 7 | .5 | mm |
| Right front | 6.8 | | mm |
| Left rear | 6 | | mm |
| Right rear | 6 | | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | <i>v</i> | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | \(\times \) | | |
| Window winder FR | | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | | | ~ |
| Number of keys | 1 | | |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | | | 1 |

Signature: