

Report ID: 26,475,320 Version: 1 11 Dec 2024 Created:

Signature: .....

Make:	Subaru	Model:	Legacy	Body Style:	Wagon		Pass	Fail	N/A
Year:	2004	<b>Registration:</b>	FBB647	<b>Reg Expiry:</b>	30 Dec 2024	Engine			
WoF Expiry:	28 Feb 2025	Odometer:	305,554 Kms	Good No:	26475320	Oil level	~		
VIN:	7A8GF0B0709045641	Next Service:	0	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for any and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:	SPSC S	-0	S SC S D		SD	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent						Operation	~		
R = rust PT = paint def				$\int$		Noise	~		
C = crack				$+ \mathbf{\nabla}$		Clutch			~
P = pin dent						CV joints	~		
* = decals	S PT SC 916			- NL	ELT SD	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC S SC S SC S SC S S S D SC						Performance	~		
		Note: som	e defects & blemishe	s may not be disr	blayed in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	•	oftyre	
Rear bumper needs alignment ,badges missing,									 
						Right front	-		-
						Left rear		.1	mm mm
			_					.5	-
Conditions During Body Inspection: Dry						5 * * *			mm
Under Carriage & Under Bonnet Inspection Comments						Spare N/A Suspension			
	boot split leaking,mind	•				Suspension performance			
	boot spire leaking, mine	in underbody sur				Steering performance	~		
						Shock absorbers	~		
							~		
						Air Conditioning / Heater			
Interior Comments						Operation V			
wear minor stains						Electrical / Accessories			
Seats	,					Head lights	~		
Carpets	wear and t	torn,,minor stain:	5,			Tail lights	~		
	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd top of das	h cracked,wear,				Wipers (front & rear)	~		
						Window winder FL	~		
Ganaral	omments					Window winder FR	~		
General Comments Drives okay,needs a service ,						Window winder RL	~		
	,					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
	ming Masheritan	Careland				Remote locking		~	
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	es	Kms: 21	4,140	Reversing camera			~
Inspected by: Donovan Matara Date: 11 Dec 2024									
Inspected by: Donovan Matara Date: 11 Dec 2024									

I have read and understood this condition guide.

Name: .....