

Make:	BMW	Model:	Х3	Body Style:	Wagon		Pass	Fail	N/A
Year:	2010	<b>Registration:</b>	JEA513	Reg Expiry:	05 Jan 2025	Engine			
WoF Expiry:	02 Dec 2025	Odometer:	97,883 Kms	Good No:	26475396	Oil level	~		
VIN:	WBAPC92090WE71911	Next Service:		Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Noise	~		
						Cooling System			
a full mechan	ical inspection prior to	Coolant condition	~						
	S		PP			Performance	~		
Key:		=				Radiator / Hoses (visual)	~		
S = scratch D = dent R = rust						Transmission			
						Operation	~		
PT = paint defe				$\left( \left  \left( \right) \right\rangle \right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	HIP				7414	CV joints	~		
* = decals SC 99						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC S PT S						Performance	~		
Podylper	action Commonts	Note: som	e defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	l depth	of tyre	s)
Top windscreen rubber seal perishing.						Left front 6.0 mm			mm
						Right front	6	.0	mm
						Left rear			mm
Conditions During Body Inspection: Dry						Right rear	9.0 mm		
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	✓		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Vehicle drove well.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Boad Conditions During Test Drive:						Central locking	2 V		
Road Conditions During Test Drive: Dry						Remote locking	• •		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	v v		
							•		
Inspected by: Aaron Johnson Date: 09 Dec 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....