

Report ID: 26,475,438 3 Version: 13 Dec 2024 Created:

Make:	Mazda	Model:	Axela	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2011	Registration:	MDU507	Reg Expiry:	23 Feb 2025	Engine	ı		
WoF Expiry:	21 Jun 2025	Odometer:	104,243 Kms	Good No:	26475438	Oil level	~		
VIN:	7AT0C13JX19102748	Next Service:	114,300kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage.	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection phor to	purchase and ti	lis can be arranged to		inarge.	Coolant condition	~		
	SC S		S S		S	Performance	~		
Key: S = scratch		=(0)		5(0)-		Radiator / Hoses (visual)	~		
						Transmission			
R = rust	S SC			10	HI IS	Operation	~		
PT = paint def	ect NP					Noise	~		
C = crack				TTY .	S SC	Clutch			~
P = pin dent	sc de				74Hb	CV joints	~		
* = decals		10		10	E S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significan	SC S		S S		S	Performance	~		
Body Inst	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	5.	.0	mm
						Right front	5.	.0	mm
						Left rear	6.	.0	mm
Conditions During Body Inspection: Dry						Right rear	6.0 mm		
						Spare	N/A		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpote						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dachhar	rd c					Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	-					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry Central locking							~		
Remote locking							~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Jason Young Date: 10 Dec 2024									

I have read and understood this condition guide.

Name:

Signature: