

Basic Vehicle Condition Guide

Report ID: 26,475,734


Version: 4

Created: 12 Dec 2024

Make: Model: Honda Accord **Body Style:** Sedan Year: 2006 Registration: DKN33 Reg Expiry: 24 Feb 2025 **Odometer: WoF Expiry: Good No:** 26 Sep 2025 189,882 Kms 26475734 VIN: JHMCL96806C210167 Next Service: 196,700 Kms Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Average		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

AC not blowing cold

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Hoani Saunders Date: 09 Dec 2024

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	v v		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			ļ
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	 es)
Left front	4.3		mm
Right front	4.8		mm
Left rear	3.0		mm
Right rear	3.7		mm
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			1
Operation		~	
Electrical / Accessories			
Head lights	~		
Tail lights			
Indicators	v		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	\(\triangle \tr		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	v		
Number of keys	1		
Central locking	· ·		
Remote locking		~	
Sat. Nav. (basic test only)			1
Reversing camera			7

Signature: