

Report ID: 26,475,799 4 Version: 12 Dec 2024 Created:

Make:	Mazda	Model:	Demio	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2010	Registration:	JGY107	Reg Expiry:	12 Aug 2025	Engine			
WoF Expiry:	22 Sep 2025	Odometer:	137,020 Kms	Good No:	26475799	Oil level	~		
VIN:	7AT0C12HX15267809	Next Service:	150,000 Kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage.	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tr	lis can be arranged to	or an additional C	narge.	Coolant condition	~		
			D PT S D PT		S	Performance	~		
Key: S = scratch		=		5(0)-		Radiator / Hoses (visual)	~		
						Transmission			
R = rust	s AR			10	SPTCW	Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack					PT SC	Clutch			~
P = pin dent	s de				2416	CV joints	~		
* = decals		10		10	ED P	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	W	C	D P PT P		D PT	Performance	~		
Body Inst	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
Rust in spare wheel well Damage to left rear guarter panel and left side of rear bumper						Left front	2.6 mm		mm
						Right front	3.7 m		mm
						Left rear	3.	.6	mm
Conditions During Body Inspection: Dry						Right rear	4.4 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Surface rust on underside of vehicle						Suspension performance	~		
						Steering performance	۲		
S						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Stains					Head lights	~		
Carpote	Card					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	2		
Dashboa	rd Access					Wipers (front & rear)	~		
	rd Average					Window winder FL	~		
	•					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry							~		
Remote locking									~
Engine Timing Mechanism: Timing Chain Evidence of Com Bolt Bonk company. No. 4 Aultichten Konst									~
Evidence of Cam Belt Replacement: Not Applicable Kms: Reversing camera									~
Inspected by: Hoani Saunders Date: 09 Dec 2024									

I have read and understood this condition guide.

Name:

Signature: