

Report ID: 26,475,866 3 Version: 17 Dec 2024 Created:

Signature: .....

Make:	Subaru	Model:	Exiga	Body Style:	Wagon		Pass	Fail	N/A
Year:	2012	Registration:	MCB690	Reg Expiry:	01 Apr 2025	Engine	I		L
WoF Expiry:	16 Apr 2025	Odometer:	137,171 Kms	Good No:	26475866	Oil level	~		
VIN:	7AT0GF1RX18019850	Next Service:	147,164km	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
	W				D	Performance	~		
Key:		-0	D DW	-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			L
D = dent	DPTC DE			TIS	HIL S	Operation	~		
R = rust PT = paint defe				$\left( \left  \right\rangle \right)$		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HIC				세비	CV joints	~		
* = decals	sc 916			- Jul	<b>HIP</b>	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC W W S S D W						Performance	~		
D. L.L.		Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Insp	pection Comments			, ,	, ,	Tyres (lowest observed tread	•	of tyre	<u> </u>
Windscreen stone chips									mm
						Right front	8.		mm
						Left rear			mm
Canditions Duving Rody Inspection.						Right rear			mm
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension	105		
	-	•				Suspension performance	~		
4 wheel driv	ve wheel					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	v		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats Good						Head lights			
	Good					Tail lights	~		
Carpets	Good						~		
Panels	Good					Dashboard warning lights Wipers (front & rear)	ン ン		
Dashboa	rd Good					Window winder FL			
						Window winder FL Window winder FR	<b>v</b>		
General Comments						Window winder FR Window winder RL	<b>v</b>		
						Window winder RL Window winder RR	<b>v</b>		
· ·						Rear view mirrors	<b>~</b>		
							<b>v</b>		
						Radio (basic test only) CD (basic test only)	<b>v</b>		
						Number of keys	1		
							1		<u> </u>
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanism: Cambelt						Remote locking	~		
Evidence of Cam Belt Replacement: Yes Kms: 71,454						Sat. Nav. (basic test only)	~		
					דער,	Reversing camera	~		
Inspected by: Rowan Fey Date: 13 Dec 2024									

I have read and understood this condition guide.

Name: .....