

Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments Rwd

		Operation	·	/	
nterior Comments		Electrical /	Electrical / Accessories		
Seats	Average	Head light	s t	/	
Carpets	Poor	Tail lights	•	/	
		Indicators	·	/	
anels	Poor	Dashboard	d warning lights	/	
Dashboard	Average	Wipers (fro	ont & rear)	/	
		Window w	vinder FL	/	
		Window v	vinder FR	/	
General Comments			vinder Bl	/	

Police car lots of holes inside and missing plastic parts, , both front body seal torn,horn N/ working, steering worn, roof anttena hole, L rear body seal torn, driver seat adjustment not working, engine oil leak, L/ front lower arm bushes leaking, steering wheel button not working,

Dry

	Number of keys	3	
Road Conditions During Test Drive: Wet	Central locking	~	
	Remote locking	~	
Engine Timing Mechanism: Timing Chain	Sat. Nav. (basic test only)		~
Evidence of Cam Belt Replacement: Not Applicable Kms:	Reversing camera	~	

Inspected by: Marlon Espena

10 Dec 2024 Date:

Left rear

Right rear

Suspension

Suspension performance

Steering performance

Air Conditioning / Heater

Window winder RR

Rear view mirrors

Radio (basic test only)

CD (basic test only)

Shock absorbers

Spare

I have read and understood this condition guide.

Name:

N/A

V

mm

mm

mm

mm

4

7

V

V

~

V

1

V

Yes

Signature: