

Report ID: 26,477,132 1 Version: 29 Dec 2024 Created:

Make:	Haval	Model:	H6	Body Style:	SUV		Pass	Fail	N/A
Year:	2018	Registration:	LKE307	Reg Expiry:	17 May 2025	Engine	1		
WoF Expiry:	31 May 2025	Odometer:	101,927 Kms	Good No:	26477132	Oil level	~		
VIN:	LGWEF6A53HH900316	Next Service:	due	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	charge.	Coolant condition	~		
	SC		S SC S SC		S SC	Performance	~		
Key:		-0	330 330		330	Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust PT = paint defect						Operation	~		
						Noise	~		
C = crack						Clutch			~
P = pin dent	sc				74116	CV joints	~		
" = decais						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W – significan	S SC		S S P SC		S D SC	Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments					Tyres (lowest observed tread depth of tyres)			es)	
					Left front 6 m			mm	
						Right front	e	6 mm	
						Left rear	6 mm		mm
Conditions During Body Inspection: Dry						Right rear	6.9 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
2wd/ engine oil leak further investigation needed						Suspension performance	~		
						Steering performance	~		
	Shock absorbers	~							
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
Remote						Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
Inspected by: Uriah Pepene Date: 29 Dec 2024									

I have read and understood this condition guide.

Name:

Signature: