

Report ID: 26,477,735 Version: 2 10 Dec 2024 Created:

Make:	Lexus	Model:	LS460	Body Style:	Sedan		Pass	Fail	N/A
Year:	2008	Registration:	MBE706	Reg Expiry:	20 Feb 2025	Engine	1	<u> </u>	1
WoF Expiry:	23 May 2025	Odometer:	132,528 Kms	Good No:	26477735	Oil level	~		
VIN:	7AT0B00JX18067954	Next Service:	126000km	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	oration is made	for ago and milaago	Darte have not	been dismonthed or	Noise	~		
diagnostic te	sting undertaken. The	vehicle has beer	driven up to 50km/h	n from cold. The	Vendor recommends	Cooling System	-		
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	s w	-0	S S		s	Radiator / Hoses (visual)	~		
S = scratch	RE	A U			The second	Transmission	•		<u> </u>
D = dent	C SC W			715		Operation	~		
R = rust PT = paint defe				\prod	JHIH	Noise	~		
C = crack				+		Clutch			~
P = pin dent					세비	CV joints	~		
* = decals	sc 916			- NL	ELIPS-	Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs S W					Performance	~		
		Note: som	e defects & blemishes	s may not be disr	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread		oftvre	
Stone chips in windscreen. Front head lights yellow and very faded, clear coat perishing.									
rioneneuu			sensining.			Right front			mm mm
						Left rear		7	
						Right rear	5 mm		
Conditions During Body Inspection: Dry							5 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
	on front tyres.								1
inner weur	on none cyres.					Suspension performance	~		
						Steering performance Shock absorbers	~		
							~		
						Air Conditioning / Heater			
Interior Comments						Operation			
Good						Electrical / Accessories			
Seats						Head lights	~		<u> </u>
Carpets	Good					Tail lights	~		<u> </u>
	Good					Indicators	~		<u> </u>
Panels						Dashboard warning lights	~		<u> </u>
Dashboa	rd Good					Wipers (front & rear)	~		<u> </u>
	-					Window winder FL	~		<u> </u>
Conorol	ommonts					Window winder FR	~		<u> </u>
General Comments Vehicle drove well.					Window winder RL	~		<u> </u>	
Service due						Window winder RR	~		<u> </u>
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		
						Number of keys	2		·
Road Con	ditions During Tes	t Drive:	Dry			Central locking	~		<u> </u>
Engina Ti	ning Machanism	Time in a f	- -			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	or Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Aaron Johnson Date: 10 Dec 2024									

I have read and understood this condition guide.

Name: