

Report ID: 26,477,816 2 Version: 30 Dec 2024 Created:

Make:	Mazda	Model:	Axela	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2009	<b>Registration:</b>	MZE850	<b>Reg Expiry:</b>	27 Sep 2024	Engine	•		
WoF Expiry:	09 Dec 2025	Odometer:	137,177 Kms	Good No:	26477816	Oil level	~		
VIN:	7AT0C13JX20103004	Next Service:	135000km	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	SC W		S SP		S	Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust						Operation	~		
PT = paint defe		r I		$\left( \left  \left( \right) \right\rangle \right)$	7011	Noise	~		
C = crack					S	Clutch			~
P = pin dent	LET HE				74116	CV joints	~		
*= decals SPT 999 S						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S W S S P SC S W S						Performance	~		
Body Incr	oction Commonts	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			es)
						Left front 9			mm
						Right front		9	mm
						Left rear		8	mm
Conditions During Body Inspection: Dry						Right rear	8 mm		mm
						Spare N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
L						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Good					Dashboard warning lights		~	
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	•					Window winder FR	~		
General Comments						Window winder RL	~		
Vehicle drove well.						Window winder RR	~		
I-Stop light	on					Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
			_			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
Inspected by: Jayden Roxburgh Date: 30 Dec 2024									

I have read and understood this condition guide.

Name: .....