

Report ID: 26,478,126 4 Version: 12 Dec 2024 Created:

Make:	Honda	Model:	CRV	Body Style:	Wagon		Pass	Fail	N/A
Year:	2009	Registration:	LJU377	Reg Expiry:	21 May 2025	Engine			
WoF Expiry:	30 Jul 2025	Odometer:	165,559 Kms	Good No:	26478126	Oil level	~		
VIN:	7AT08G7HX18201056	Next Service:	168,000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	SW DW	\square		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	sc di			715	HILW	Operation	~		
PT = paint defe				$\left[\right] \left[\right]$		Noise	~		
C = crack						Clutch			~
P = pin dent	HID				74114	CV joints	~		
* = decals	sc 916			The second		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs W DW DW SW						Performance	~		
Padulaa		Note: som	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			es)
Good								mm	
						Right front	8.	-	mm
						Left rear	7.		mm
Conditions During Body Inspection: Dry						Right rear	7.5 mm		mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Card						Suspension performance	~		
Good						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Seats Good					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	1					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
Good						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		I
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic te									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
						-			1
Inspected by: Tyler Le Bherz Date: 09 Dec 2024									

I have read and understood this condition guide.

Name:

Signature: