

Report ID: 26,478,283 7 Version: 12 Dec 2024 Created:

Make:	Nissan	Model:	Murano	Body Style:	SUV		Pass	Fail	N/A
Year:	2010	Registration:	FQC813	Reg Expiry:	19 Mar 2025	Engine	1	i	
WoF Expiry:	11 Nov 2025	Odometer:	125,437 Kms	Good No:	26478283	Oil level	~		
VIN:	JN1TANZ51A0004358	Next Service:	135,050kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	S SC S		SP SDP	S	S	Performance	~		
Key:	1350 []3	-0		-01-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	S PT SC			710	HIL SW	Operation	~		
PT = paint defe	ect NP	r I				Noise	~		
C = crack					S SC	Clutch			~
P = pin dent	s sc dl				7414	CV joints	~		
* = decals		10		10	ED S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant scuffs S P SC S W S D P W S W						Performance	~		
Body Inst	pection Comments	Note: som	ne defects & blemishes	s may not be disp	blayed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			es)
					Left front 4.0		.0	mm	
						Right front	4	.0	mm
						Left rear	4	.0	mm
Conditions During Body Inspection: Dry						Right rear	5.0 m		mm
						Spare N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Correcto						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dachher-						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
Small plastic cover missing off interior panel on tailgate.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry Central locking									
Engine Timing Mechanism: Timing Chain						Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	oi cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Jason Young Date: 10 Dec 2024									

I have read and understood this condition guide.

Name:

Signature: